
Radon Inspection Report

Test Location:

Silverton Middle School
714 Schlador St.
Silverton , OREGON 97381

Test For:

Bldg. Type: Educational

Type: Post-Mitigation

Inspected By:

12839 NE Airport Way
Portland, OR 97230
5034214813

Test Result: Pass

Overall Average:

0.6 pCi/l

EPA Average:

0.6 pCi/l

Test Device Details:

Serial Number: 239145025
Model Number: 1028XP
Last Calibration: 03/13/2019
Next Calibration: 03/13/2020
Cal-Factors: 3.0
Motion Error: Yes

Test Site Condition:

Structure Type: Middle School
Mitigation Sys: Installed and Active

Test Summary:


<u>CRM Location:</u> Nurse Office	<u>Start:</u> 04/09/2019 04:14 PM	<u>Stop:</u> 04/12/2019 07:14 AM	<u>Interval:</u> 1 hr	<u>Duration:</u> 63 hr
Radon Concentration:	<u>Min:</u> 0.0	<u>Max:</u> 2.0	<u>Average:</u> 0.6	<u>Measurement Units:</u> pCi/l

Comments:

Lic/Cert Signature

Inspection Report Date: 04/12/2019

Radon Inspection Chart



Test Result: Pass

Test Location: 714 Schlador St. Silverton , OREGON 97381

Inspection Report Date: 04/12/2019

Test Table

Date/Time	Radon(pCi/l)	Temp(F)	Pres(inHg)	Humidity(%)	Flags
04/09/19 05:14 PM	0.0	-	-	-	M
04/09/19 06:14 PM	0.3	-	-	-	-
04/09/19 07:14 PM	0.3	-	-	-	-
04/09/19 08:14 PM	0.3	-	-	-	-
04/09/19 09:14 PM	0.0	-	-	-	-
04/09/19 10:14 PM	0.7	-	-	-	-
04/09/19 11:14 PM	0.7	-	-	-	-
04/10/19 12:14 AM	1.0	-	-	-	-
04/10/19 01:14 AM	0.7	-	-	-	-
04/10/19 02:14 AM	1.3	-	-	-	-
04/10/19 03:14 AM	1.0	-	-	-	-
04/10/19 04:14 AM	0.0	-	-	-	-
04/10/19 05:14 AM	0.3	-	-	-	-
04/10/19 06:14 AM	0.3	-	-	-	-
04/10/19 07:14 AM	1.6	-	-	-	-
04/10/19 08:14 AM	1.0	-	-	-	-
04/10/19 09:14 AM	0.3	-	-	-	-
04/10/19 10:14 AM	0.0	-	-	-	-
04/10/19 11:14 AM	0.7	-	-	-	-
04/10/19 12:14 PM	0.0	-	-	-	-
04/10/19 01:14 PM	0.0	-	-	-	-
04/10/19 02:14 PM	0.0	-	-	-	-
04/10/19 03:14 PM	0.0	-	-	-	-
04/10/19 04:14 PM	0.0	-	-	-	-
04/10/19 05:14 PM	0.7	-	-	-	-
04/10/19 06:14 PM	0.3	-	-	-	-
04/10/19 07:14 PM	0.7	-	-	-	-
04/10/19 08:14 PM	0.7	-	-	-	-
04/10/19 09:14 PM	0.7	-	-	-	-
04/10/19 10:14 PM	1.3	-	-	-	-
04/10/19 11:14 PM	0.3	-	-	-	-
04/11/19 12:14 AM	0.7	-	-	-	-
04/11/19 01:14 AM	0.7	-	-	-	-
04/11/19 02:14 AM	1.6	-	-	-	-
04/11/19 03:14 AM	0.7	-	-	-	-
04/11/19 04:14 AM	1.3	-	-	-	-
04/11/19 05:14 AM	1.3	-	-	-	-
04/11/19 06:14 AM	0.7	-	-	-	-
04/11/19 07:14 AM	2.0	-	-	-	-
04/11/19 08:14 AM	1.3	-	-	-	-
04/11/19 09:14 AM	0.7	-	-	-	-
04/11/19 10:14 AM	0.0	-	-	-	-
04/11/19 11:14 AM	0.0	-	-	-	-
04/11/19 12:14 PM	0.7	-	-	-	-

Test Result: Pass

Test Location: 714 Schlador St. Silverton , OREGON 97381

Inspection Report Date: 04/12/2019

Test Table

<u>Date/Time</u>	<u>Radon(pCi/l)</u>	<u>Temp(F)</u>	<u>Pres(inHg)</u>	<u>Humidity(%)</u>	<u>Flags</u>
04/11/19 01:14 PM	1.0	-	-	-	M
04/11/19 02:14 PM	0.7	-	-	-	-
04/11/19 03:14 PM	0.3	-	-	-	-
04/11/19 04:14 PM	0.0	-	-	-	-
04/11/19 05:14 PM	0.0	-	-	-	-
04/11/19 06:14 PM	0.7	-	-	-	-
04/11/19 07:14 PM	0.7	-	-	-	-
04/11/19 08:14 PM	0.3	-	-	-	-
04/11/19 09:14 PM	0.0	-	-	-	-
04/11/19 10:14 PM	0.0	-	-	-	-
04/11/19 11:14 PM	1.0	-	-	-	-
04/12/19 12:14 AM	0.7	-	-	-	-
04/12/19 01:14 AM	1.0	-	-	-	-
04/12/19 02:14 AM	1.0	-	-	-	-
04/12/19 03:14 AM	0.3	-	-	-	-
04/12/19 04:14 AM	1.6	-	-	-	-
04/12/19 05:14 AM	1.0	-	-	-	-
04/12/19 06:14 AM	0.0	-	-	-	-
04/12/19 07:14 AM	0.0	-	-	-	-

Test Result: Pass

Test Location: 714 Schlador St. Silverton , OREGON 97381

Inspection Report Date: 04/12/2019