

---

## Radon Inspection Report

---

**Test Location:**

Silverton Middle School  
714 Schlador St.  
Silverton, OREGON 97381

**Test For:**

Bldg. Type: Educational

Type: Post-Mitigation

**Inspected By:**

Cascade Radon, 12839 NE Airport Way  
PORTLAND OR  
503-421-4813

---

## Test Result: Pass

**Overall Average:**

**3.1 pCi/l**

**EPA Average:**

**3.2 pCi/l**

---

**Test Device Details:**

Serial Number: 240235012  
Model Number: 1028XP  
Last Calibration: 03/13/2019  
Next Calibration: 03/13/2020  
Cal-Factors: 3.0  
Motion Error: Yes

**Test Site Condition:**

Structure Type: Middle school  
Mitigation Sys: Installed and Active

**Test Summary:**

<u>CRM Location:</u> Boys locker room	<u>Start:</u> 04/09/2019 04:36 PM	<u>Stop:</u> 04/12/2019 07:36 AM	<u>Interval:</u> 1 hr	<u>Duration:</u> 63 hr
Radon Concentration:	<u>Min:</u> 0.3	<u>Max:</u> 6.0	<u>Average:</u> 3.1	<u>Measurement Units:</u> pCi/l


---

**Comments:**

Lic/Cert Signature

Inspection Report Date: 04/12/2019

### Radon Inspection Chart



**Test Result: Pass**

**Test Location:** 714 Schlador St. Silverton, OREGON 97381

**Inspection Report Date:** 04/12/2019

### Test Table

Date/Time	Radon(pCi/l)	Temp(F)	Pres(inHg)	Humidity(%)	Flags
04/09/19 05:36 PM	1.3	-	-	-	-
04/09/19 06:36 PM	1.7	-	-	-	-
04/09/19 07:36 PM	0.3	-	-	-	-
04/09/19 08:36 PM	2.3	-	-	-	-
04/09/19 09:36 PM	1.7	-	-	-	-
04/09/19 10:36 PM	1.3	-	-	-	-
04/09/19 11:36 PM	2.7	-	-	-	-
04/10/19 12:36 AM	1.3	-	-	-	-
04/10/19 01:36 AM	1.7	-	-	-	-
04/10/19 02:36 AM	2.3	-	-	-	-
04/10/19 03:36 AM	2.0	-	-	-	-
04/10/19 04:36 AM	2.0	-	-	-	-
04/10/19 05:36 AM	2.0	-	-	-	-
04/10/19 06:36 AM	3.0	-	-	-	-
04/10/19 07:36 AM	3.0	-	-	-	-
04/10/19 08:36 AM	2.3	-	-	-	-
04/10/19 09:36 AM	2.3	-	-	-	M
04/10/19 10:36 AM	2.0	-	-	-	M
04/10/19 11:36 AM	1.0	-	-	-	M
04/10/19 12:36 PM	3.0	-	-	-	-
04/10/19 01:36 PM	3.0	-	-	-	M
04/10/19 02:36 PM	3.3	-	-	-	M
04/10/19 03:36 PM	4.0	-	-	-	-
04/10/19 04:36 PM	4.3	-	-	-	-
04/10/19 05:36 PM	4.0	-	-	-	-
04/10/19 06:36 PM	4.0	-	-	-	-
04/10/19 07:36 PM	4.3	-	-	-	-
04/10/19 08:36 PM	3.0	-	-	-	-
04/10/19 09:36 PM	4.7	-	-	-	-
04/10/19 10:36 PM	4.7	-	-	-	-
04/10/19 11:36 PM	3.3	-	-	-	-
04/11/19 12:36 AM	4.0	-	-	-	-
04/11/19 01:36 AM	5.0	-	-	-	-
04/11/19 02:36 AM	3.0	-	-	-	-
04/11/19 03:36 AM	3.3	-	-	-	-
04/11/19 04:36 AM	5.4	-	-	-	-
04/11/19 05:36 AM	4.0	-	-	-	-
04/11/19 06:36 AM	4.3	-	-	-	-
04/11/19 07:36 AM	1.0	-	-	-	-
04/11/19 08:36 AM	3.3	-	-	-	-
04/11/19 09:36 AM	2.7	-	-	-	-
04/11/19 10:36 AM	4.0	-	-	-	-
04/11/19 11:36 AM	3.3	-	-	-	M
04/11/19 12:36 PM	1.3	-	-	-	M

### Test Result: Pass

**Test Location:** 714 Schlador St. Silverton, OREGON 97381

**Inspection Report Date:** 04/12/2019

---

### Test Table

<u>Date/Time</u>	<u>Radon(pCi/l)</u>	<u>Temp(F)</u>	<u>Pres(inHg)</u>	<u>Humidity(%)</u>	<u>Flags</u>
04/11/19 01:36 PM	3.7	-	-	-	M
04/11/19 02:36 PM	1.7	-	-	-	M
04/11/19 03:36 PM	4.3	-	-	-	M
04/11/19 04:36 PM	5.4	-	-	-	-
04/11/19 05:36 PM	4.3	-	-	-	-
04/11/19 06:36 PM	5.4	-	-	-	-
04/11/19 07:36 PM	5.0	-	-	-	-
04/11/19 08:36 PM	6.0	-	-	-	-
04/11/19 09:36 PM	4.3	-	-	-	-
04/11/19 10:36 PM	4.7	-	-	-	-
04/11/19 11:36 PM	5.0	-	-	-	-
04/12/19 12:36 AM	1.7	-	-	-	-
04/12/19 01:36 AM	2.7	-	-	-	-
04/12/19 02:36 AM	3.3	-	-	-	-
04/12/19 03:36 AM	4.0	-	-	-	-
04/12/19 04:36 AM	3.3	-	-	-	-
04/12/19 05:36 AM	3.0	-	-	-	-
04/12/19 06:36 AM	1.3	-	-	-	-
04/12/19 07:36 AM	1.0	-	-	-	-

---

### Test Result: Pass

**Test Location:** 714 Schlador St. Silverton, OREGON 97381

**Inspection Report Date:** 04/12/2019