

---

# Radon Inspection Report

---

**Test Location:**

Silverton Middle School  
714 Schlador St.  
Silverton, OREGON 97381

**Test For:**

Type: Post-Mitigation

**Inspected By:**

12839 NE Airport Way  
Portland, OR 97230  
5034214813

Bldg. Type: Educational

---

## Test Result: Pass

**Overall Average:**

**0.6 pCi/l**

**EPA Average:**

**0.6 pCi/l**

---

**Test Device Details:**

Serial Number: 239145025  
Model Number: 1028XP  
Last Calibration: 03/13/2019  
Next Calibration: 03/13/2020  
Cal-Factors: 3.0  
Motion Error: Yes

**Test Site Condition:**

Structure Type: Middle School  
Mitigation Sys: Installed and Active

**Test Summary:**

<u>CRM Location:</u> Girls Locker Room	<u>Start:</u> 04/15/2019 11:17 AM	<u>Stop:</u> 04/19/2019 04:17 PM	<u>Interval:</u> 1 hr	<u>Duration:</u> 101 hr
Radon Concentration:	<u>Min:</u> 0.0	<u>Max:</u> 2.0	<u>Average:</u> 0.6	<u>Measurement Units:</u> pCi/l


---

**Comments:**

Lic/Cert Signature

Inspection Report Date: 04/22/2019

### Radon Inspection Chart



**Test Result: Pass**

**Test Location:** 714 Schlador St. Silverton, OREGON 97381

**Inspection Report Date:** 04/22/2019

### Test Table

Date/Time	Radon(pCi/l)	Temp(F)	Pres(inHg)	Humidity(%)	Flags
04/15/19 12:17 PM	0.0	-	-	-	M
04/15/19 01:17 PM	0.3	-	-	-	M
04/15/19 02:17 PM	0.3	-	-	-	-
04/15/19 03:17 PM	0.7	-	-	-	-
04/15/19 04:17 PM	0.3	-	-	-	-
04/15/19 05:17 PM	0.3	-	-	-	-
04/15/19 06:17 PM	1.0	-	-	-	-
04/15/19 07:17 PM	0.7	-	-	-	-
04/15/19 08:17 PM	1.3	-	-	-	-
04/15/19 09:17 PM	0.3	-	-	-	-
04/15/19 10:17 PM	0.7	-	-	-	-
04/15/19 11:17 PM	0.7	-	-	-	-
04/16/19 12:17 AM	0.3	-	-	-	-
04/16/19 01:17 AM	0.7	-	-	-	-
04/16/19 02:17 AM	0.3	-	-	-	-
04/16/19 03:17 AM	0.3	-	-	-	-
04/16/19 04:17 AM	0.0	-	-	-	-
04/16/19 05:17 AM	0.7	-	-	-	-
04/16/19 06:17 AM	0.7	-	-	-	-
04/16/19 07:17 AM	1.3	-	-	-	-
04/16/19 08:17 AM	1.0	-	-	-	-
04/16/19 09:17 AM	0.3	-	-	-	-
04/16/19 10:17 AM	0.3	-	-	-	M
04/16/19 11:17 AM	0.7	-	-	-	M
04/16/19 12:17 PM	0.7	-	-	-	M
04/16/19 01:17 PM	0.7	-	-	-	-
04/16/19 02:17 PM	0.0	-	-	-	-
04/16/19 03:17 PM	0.0	-	-	-	-
04/16/19 04:17 PM	0.0	-	-	-	-
04/16/19 05:17 PM	1.0	-	-	-	-
04/16/19 06:17 PM	0.7	-	-	-	-
04/16/19 07:17 PM	0.0	-	-	-	-
04/16/19 08:17 PM	0.7	-	-	-	-
04/16/19 09:17 PM	0.7	-	-	-	-
04/16/19 10:17 PM	0.0	-	-	-	-
04/16/19 11:17 PM	0.7	-	-	-	-
04/17/19 12:17 AM	0.3	-	-	-	-
04/17/19 01:17 AM	1.3	-	-	-	-
04/17/19 02:17 AM	1.6	-	-	-	-
04/17/19 03:17 AM	0.7	-	-	-	-
04/17/19 04:17 AM	1.0	-	-	-	-
04/17/19 05:17 AM	0.3	-	-	-	-
04/17/19 06:17 AM	0.0	-	-	-	-
04/17/19 07:17 AM	1.6	-	-	-	-

**Test Result: Pass**

**Test Location:** 714 Schlador St. Silverton, OREGON 97381

**Inspection Report Date:** 04/22/2019

### Test Table

Date/Time	Radon(pCi/l)	Temp(F)	Pres(inHg)	Humidity(%)	Flags
04/17/19 08:17 AM	1.0	-	-	-	-
04/17/19 09:17 AM	1.0	-	-	-	-
04/17/19 10:17 AM	0.3	-	-	-	-
04/17/19 11:17 AM	1.6	-	-	-	-
04/17/19 12:17 PM	0.7	-	-	-	-
04/17/19 01:17 PM	0.0	-	-	-	-
04/17/19 02:17 PM	0.0	-	-	-	-
04/17/19 03:17 PM	0.0	-	-	-	-
04/17/19 04:17 PM	0.7	-	-	-	-
04/17/19 05:17 PM	0.7	-	-	-	-
04/17/19 06:17 PM	0.7	-	-	-	-
04/17/19 07:17 PM	0.3	-	-	-	-
04/17/19 08:17 PM	0.3	-	-	-	-
04/17/19 09:17 PM	1.6	-	-	-	-
04/17/19 10:17 PM	1.0	-	-	-	-
04/17/19 11:17 PM	0.3	-	-	-	-
04/18/19 12:17 AM	0.7	-	-	-	-
04/18/19 01:17 AM	2.0	-	-	-	-
04/18/19 02:17 AM	1.0	-	-	-	-
04/18/19 03:17 AM	0.7	-	-	-	-
04/18/19 04:17 AM	0.3	-	-	-	-
04/18/19 05:17 AM	0.0	-	-	-	-
04/18/19 06:17 AM	0.3	-	-	-	-
04/18/19 07:17 AM	0.7	-	-	-	-
04/18/19 08:17 AM	0.0	-	-	-	M
04/18/19 09:17 AM	1.0	-	-	-	-
04/18/19 10:17 AM	1.3	-	-	-	M
04/18/19 11:17 AM	1.6	-	-	-	-
04/18/19 12:17 PM	1.3	-	-	-	-
04/18/19 01:17 PM	0.3	-	-	-	M
04/18/19 02:17 PM	0.0	-	-	-	-
04/18/19 03:17 PM	0.0	-	-	-	M
04/18/19 04:17 PM	0.7	-	-	-	-
04/18/19 05:17 PM	0.7	-	-	-	-
04/18/19 06:17 PM	0.0	-	-	-	-
04/18/19 07:17 PM	0.7	-	-	-	-
04/18/19 08:17 PM	0.3	-	-	-	-
04/18/19 09:17 PM	0.0	-	-	-	-
04/18/19 10:17 PM	0.7	-	-	-	-
04/18/19 11:17 PM	0.3	-	-	-	-
04/19/19 12:17 AM	0.0	-	-	-	-
04/19/19 01:17 AM	1.3	-	-	-	-
04/19/19 02:17 AM	1.0	-	-	-	-
04/19/19 03:17 AM	1.0	-	-	-	-

### Test Result: Pass

Test Location: 714 Schlador St. Silverton, OREGON 97381

Inspection Report Date: 04/22/2019

---

### Test Table

---

<u>Date/Time</u>	<u>Radon(pCi/l)</u>	<u>Temp(F)</u>	<u>Pres(inHg)</u>	<u>Humidity(%)</u>	<u>Flags</u>
04/19/19 04:17 AM	0.0	-	-	-	-
04/19/19 05:17 AM	0.0	-	-	-	-
04/19/19 06:17 AM	0.0	-	-	-	-
04/19/19 07:17 AM	1.0	-	-	-	-
04/19/19 08:17 AM	0.7	-	-	-	-
04/19/19 09:17 AM	0.0	-	-	-	-
04/19/19 10:17 AM	0.7	-	-	-	M
04/19/19 11:17 AM	0.3	-	-	-	-
04/19/19 12:17 PM	0.7	-	-	-	-
04/19/19 01:17 PM	0.3	-	-	-	-
04/19/19 02:17 PM	1.6	-	-	-	M
04/19/19 03:17 PM	0.7	-	-	-	-
04/19/19 04:17 PM	0.7	-	-	-	-

---

**Test Result: Pass**

**Test Location:** 714 Schlador St. Silverton, OREGON 97381

**Inspection Report Date:** 04/22/2019

---